

8.24 ALARM 417 (DIGITAL SERVO SYSTEM IS ABNORMAL)

● Causes

- 1 Confirm the setting value of the following parameters:

PRM 2020 : Motor format number

PRM 2022 : Motor rotation direction

PRM 2023 : Number of pulses of velocity feedbacks

PRM 2024 : Number of pulses of position feedback

PRM 1023 : Servo axis number

PRM 2084 : Flexible feed gear ratio

PRM 2085 : Flexible feed gear ratio

Confirm the details with diagnosis function of CNC side.

- 2 Change the setting of this parameter to 0.

PRM 2047 : Observer parameter

- 3 Perform initial setting of digital servo parameters.

Refer to section 5.1 “Initial Setting of Servo Parameters” .

This data indicates the cause of servo alarm No. 417, detected by the NC. If the alarm is detected by the servo, the PRM bit (bit 4 of DGN No. 0203) is set to 1.

#7	#6	#5	#4	#3	#2	#1	#0
0280		AXS		DIR	PLS	PLC	MOT

#0(MOT) : The motor type specified in parameter No. 2020 falls outside the predetermined range.

#2(PLC) : The number of velocity feedback pulses per motor revolution, specified in parameter No. 2023, is zero or less. The value is invalid.

#3(PLS) : The number of position feedback pulses per motor revolution, specified in parameter No. 2024, is zero or less. The value is invalid.

#4(DIR) : The wrong direction of rotation for the motor is specified in parameter No. 2022 (the value is other than 111 or -111).

#6(AXS) : In parameter No. 1023 (servo axis number), a value that falls outside the range of 1 to the number of controlled axes is specified. (For example, 4 is specified instead of 3.) Alternatively, the values specified in the parameter are not consecutive.