

8.24 ALARM 417 (DIGITAL SERVO SYSTEM IS ABNORMAL)

Digital servo parameters are abnormal.

(Digital servo parameters are set incorrectly.)

When alarm 315 is occurred at the same time, check the cause of alarm 351 of section 9.16.

• Causes

- 1 Confirm the setting value of the following parameters:
 - PRM 2020 : Motor format number
 - PRM 2022 : Motor rotation direction
 - PRM 2023 : Number of pulses of velocity feedbacks
 - PRM 2024 : Number of pulses of position feedback
 - PRM 1023 : Servo axis number
 - PRM 2084 : Flexible feed gear ratio
 - PRM 2085 : Flexible feed gear ratio

Confirm the details with diagnosis function of CNC side.
- 2 Change the setting of this parameter to 0.
 - PRM 2047 : Observer parameter
- 3 Perform initial setting of digital servo parameters.

Refer to section 5.1 “Initial Setting of Servo Parameters” .

This data indicates the cause of servo alarm No. 417, detected by the NC. If the alarm is detected by the servo, the PRM bit (bit 4 of DGN No. 0203) is set to 1.

	#7	#6	#5	#4	#3	#2	#1	#0
0280		AXS		DIR	PLS	PLC		MOT

- #0(MOT)** : The motor type specified in parameter No. 2020 falls outside the predetermined range.
- #2(PLC)** : The number of velocity feedback pulses per motor revolution, specified in parameter No. 2023, is zero or less. The value is invalid.
- #3(PLS)** : The number of position feedback pulses per motor revolution, specified in parameter No. 2024, is zero or less. The value is invalid.
- #4(DIR)** : The wrong direction of rotation for the motor is specified in parameter No. 2022 (the value is other than 111 or -111).
- #6(AXS)** : In parameter No. 1023 (servo axis number), a value that falls outside the range of 1 to the number of controlled axes is specified. (For example, 4 is specified instead of 3.) Alternatively, the values specified in the parameter are not consecutive.